

BOAT REPAIR RECEIPT

John Bucher

PHONE# 954-309-8292

NAME	Frank Carbone
ADDRESS	
CITY,STATE	

QUAN.	PART NO.	NAME OF PART	PRICE	CUSTOMER'S INFORMATION		
				DATE	CUSTOMER'S ORDER NO.	WHEN PROMISED
				4/22/2025		
				YEAR,MAKE,MODEL		
				Tracker		
				LICENSE NO		HRS
				SERIAL NO.		
				MOTOR NO.		
				Mercury 115 proxs 4st		
				HOME PHONE #	CELL PHONE #	BUDGET
				WORK PERFORMED		
				Diagnose no shift in gearcase, found fwd bearing		
				retainer ring jammed up in shift slide, (bearing sh-		
				ifted inside gear), found excessive wear on fwd gear		
				bearing (bearing cage damaged), gear oil black (burnt		
				smell) in color, lots of material wrapped around prop		
				shaft between thrust washer & seal (no water in		
				gear oil), replace both fwd gear bearings & retainer,		
				clean & assemble case with new seals & impeller.		
TOTAL PARTS			\$-	GAS,OIL & GREASE		PARTS
MECHANICS RECOMMENDATIONS				GALS. GAS		2, parts cleaner spray
Gearcase internals (shafts, gears ect..) are in serviceable				QTS. OIL		\$20.00
condition (other than items listed) but show high amount				LBS. GREASE		
of wear (attached pictures),				TOTAL		
				PRICE GAS,OIL,GREASE		
				GAS	\$45.00	
This gearcase is the standard gearcase for this engine, due				OIL		
to the nature of use (commercial use) a command thrust				GREASE		
(larger) gearcase should be used along with proper gear				TOTAL		
oil change intervals (every 100hrs max).						TOTAL \$20.00
						LABOR ONLY \$550.00
Clear out water pressure gauge line & install gear case						PARTS \$-
						PARTS \$20.00
						GAS,OIL,GREASE \$45.00
Customer supplied parts						
						TOTAL \$615.00
				AUTHORIZED BY		TOTAL \$615.00
